

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA01711CH

This certificate issued to Proscan Avionics, Inc.
8891 Airport Road, C-10
Blaine, MN 55449

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.
(See Type Certificate Data Sheet No. 3A15 for complete certification basis)

Original Product -- Type Certificate Number : 3A15
Make : Raytheon Aircraft Co. (Beech)
Model : F33A, F33C, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, A36

Description of Type Design Change:

Installation of Proscan Avionics FSM2000 Flight Systems Monitor in accordance with Proscan Avionics Installation Manual, 80-FSMIM01-00, Rev. 2, dated October 9, 2002, or later FAA approved revisions.

Limitations and Conditions :

1. Compatibility of this design change with previously approved modifications must be determined by the installer.
2. Airplane Flight Manual Supplement, Proscan Avionics Document 80-FSMAFMS-00, Rev. Orig., dated October 10, 2002, or later approved revision, is required on board the modified aircraft.
3. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : March 15, 2001

Date reissued :

Date of issuance : October 10, 2002

Date amended :



By direction of the Administrator

Charles L. Smalley
(Signature)

Charles L. Smalley
Manager, Systems and Flight Test Branch
Chicago Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.